

BMW CDR 17.0 Coverage Sept 2016

<u>Model</u>	<u>Location</u>						
Last 3 digits of Bosch CDR adapter /cable number shown		<u>2012</u>	<u>2013</u>	<u>2014</u>	<u>2015</u>	<u>2016</u>	<u>2017</u>
BMW	All BMW require 387 Adapter for DTM						
1 Series					not covered		
2 Series	Driver side, behind IP, rt of strg			796			
3 Series	Driver side, behind IP, rt of strg		796				
Active Hybrid 3	Passenger side, behind the glove box		796				
4 Series	Driver side, behind IP, rt of strg			796			
5 Series	Passenger side, behind the glove box		796				
6 Series	Passenger side, behind the glove box		796				
7 Series	Passenger side, behind the glove box		796			500/796	500/822
X3 xDrive	Passenger side, behind the glove box		796				
X5	Center Tunnel, Between Seats			796			
X1	Center Tunnel, Between Seats				798	500/798	500/807
X3, X4, X6	See Help File - Various				796		
Z4	Center Tunnel, Under Dash				798		
i3, i8	See Service Manual			500/807			
The source data for this chart is the Bosch CDR help file for Version 17.0							
Always consult the latest help file for the most accurate coverage							
Copyright Ruth Consulting LLC 2015 - Authorized for distribution by UNF-IPTM,							
Virginia Tech, SAE, MSU & Schoolcraft College, IATAI, PSP & MATAI							